



Please be advised that during periods of increased traffic, aircraft with wingspans greater than 79 feet are likely to experience increased departure delays at the Boca Raton Airport (BCT).

These delays are associated with the following restriction published within the chart supplement for BCT:

Aircraft with wingspan greater than 79 feet and/or an approach speed greater than 140 knots are prohibited from using Runway 5/23 while aircraft with a wingspan greater than 79 feet occupies Taxiway B. Aircraft with a wingspan greater than 79 feet must remain clear of Taxiway B while aircraft with a wingspan greater than 79 feet are approaching or departing Runway 5/23.

The Boca Raton Airport Authority recommends considering this restriction when scheduling aircraft with wingspan greater than 79 feet into BCT to reduce any potential arrival and departure delays.